TIROCKREPSATED PLANT EMD OPERATING PROCEDURES MANUAL

Manual No.: Procedure No.: 5-21000-OPS-GT

Table of Contents, Rev 30

1 of 3

Effective Date: 12/14/92
Organization: Environmental Management

THIS IS ONE VOLUME OF A SIX VOLUME SET WHICH INCLUDES:

Page:

VOLUME I: FIELD OPERATIONS (FO)
VOLUME II: GROUNDWATER (GW)
VOLUME III: GEOTECHNICAL (GT)
VOLUME IV: SURFACE WATER (SW)
VOLUME V: ECOLOGY (EE)
VOLUME VI: AIR (AP)

TABLE OF CONTENTS FOR VOLUME III: GEOTECHNICAL

Procedure No.	Title	Rev. <u>No.</u>	Effective <u>Date</u>
GT.01	Logging Alluvial and Bedrock Material	2	05/12/92
DCN 92.01	Specialized Logging Form	2	11/13/92
GT.02	Drilling and Sampling Using Hollow Stem Auger Techniques	2	05/12/92
DCN 92.01	Superseded by DCN 92.03	2	07/27/92
DCN 92.02	Superseded by DCN 92.03	2	07/27/92
DCN 92.03	Addition of the Drum Characterization	2	07/27/92
DCN 92.04	Prevention of Down Hole Contamination	2 .	08/26/92
DCN 92.05	Field Modification	2	12/04/92
GT.03	Isolating Bedrock from Alluvium with Grouted Surface Casing	2	05/12/92
DCN 92.03	Expired	2	09/03/92
GT.04	Rotary Drilling and Rock Coring	2	05/12/92

PER R.B. HOFFMAN, CLASSIFICATION OFFICE JUNE 11, 1991

11

ROCKY FLATS PLANT EMD OPERATING PROCEDURES MANUAL Manual No.: Procedure No.: Page:

Effective Date: Organization:

5-21000-OPS-GT Table of Contents, Rev 30 2 of 3

12/14/92

Environmental Management

Procedure No.	<u>Title</u>	Rev. <u>No</u> .	Effective Date
GT.05	Plugging and Abandonment of Boreholes	2	05/12/92
DCN 92.01	Field Modification	2	12/09/92
GT.06	Monitoring Wells and Piezometer Installation	2	05/12/92
DCN 92.05	Schematic Diagram Land Fill Methane Wells	2	06/04/92
DCN 92.06	Field Modification	2	11/12/92
GT.07	Logging and Sampling of Test Pits and Trenches	2	05/12/92
GT.08	Surface Soil Sampling	2	05/12/92
DCN 92.01	Clarification of Soil Sampling	2	09/03/92
DCN 92.02	Consistency Change	2	10/12/92
GT.09	Soil Gas Sampling and Field Analysis	2 '	05/12/92
GT.10	Borehole Clearing	2	05/12/92
GT.11	Plugging and Abandonment of Wells	2	05/12/92
GT.15	Geophysical Borehole Logging	2	05/12/92
G T.17	Land Surveying	2	05/12/92
GT.18	Surface Geophysical Surveys	2	05/12/92
DCN 92.01	Surface Magnetic Surveys Procedure	2	09/30/92
DCN 92.02	Modification to Stacking Requirements	2	10/15/92
DCN 92.03	Modification to Method of Taking Readings	. 2	10/15/92
GT.19	Field Gas Chromatographs	2	05/12/92

ROCKY FLATS PLANT EMD OPERATING PROCEDURES MANUAL

Manual No.: Procedure No.:

Page:

Effective Date: Organization:

5-21000-OPS-GT Table of Contents, Rev 30

3 of 3

12/14/92

Environmental Management

Procedure No.	<u>Title</u>	Rev. No.	Effective Date
GT.20	Procedures for Soil Interstitial Water Sampling and Sampler Installation	2	05/12/92
GT.21	Cone Penetrometer Testing	1	05/12/92
GT.24	Approval Process for Construction Activities on or Near Individual Hazardous Substance		the same
	Sites (IHSSs)	0	05/12/92

5413 12/15/52 This is a #22 CONTROLLED DOCUMENT ENVIRONMENTAL MANAGEMENT
EG&G - ROCKY FLATS PLANT DOCUMENT CHANGE NOTICE (DCN)
ENVIRONMENTAL MANAGEMENT
This is a RED Stamp

Frocedure Number 5-21000-OPS-GT.2, Rev. 2

Page 1 of 1

Title						Date	DCN Num	nber
	and Sam	pling Using H	ollow-Stem A		12/04/92 5-21000-OPS-92.05			
Expires	12/	4/93	P	rocedure Rev	vision Required	X Yes No)	
Scope Lin	nitation	Areas outside	of IHSSs					·
	· · · · · · · · · · · · · · · · · · ·						· · · · · · · · · · · · · · · · · · ·	
Item Number	Page	Step or Paragraph		(Use D	CN CONTINUA	Changes TION SHEET for Ac	lditional Spa	ce)
1	11 of	5.3.4 paragraph 1	Reference D	CN 92.03 for	section 5.3.4		···	
	14		(NOTE: In a	reas outside	of IHSSs, no fur	g "When obtaining ther characterization an's Field Sampling	n sampling v	vill be
. * .								· ·
•		·						
· · · · ·						•		
							e e	
				**			•	
ustificatio	n (Reaso	on for Change	– Provide Nu	mbers To Re	eference Corress	conding Items Above	<u> </u>	
er DOE I	etter of N	ovember 30,		burger to Be		M:13364) granting a		modifying
·					. *	DOCUMENT CLASSI PER R.B. HOFFMAI JUN	FICATION RI N, CLASSIFIC IE 11, 1991	EVIEW WAIVER ATION OFFICE
Concurre	ence	Organizatio	on Req	Date	Concurrence	Organization	Req	Date
Baugh	nymu	QAPM	X	12/8/92	a L Parmy	User	Х	12/4/92
· · · J	-9				D.M/Let	USER	×	12/7/92

<i>]</i> //_(<i></i>	sible Manage		7-92	Is Posting Req	10 12 7 9 2	- 20/1	Date Posted
N Form 001	•					upon re	ceipt	

CONTROLLED DOCUMENT ENVIRONMENTAL MANAGEMENT EG&G - ROCKY FLATS PLANT DOCUMENT CHANGE NOTICE (DCN) ENVIRONMENTAL MANAGEMENT This is a DED Co-----Estis 12/15/92 This is a

This is a RED Stamp

Procedure Number 5-21000-OPS-GT.5, Rev. 2

Page 1 of 1

Title			, D		÷.		Date		DCN Num	ber DPS- <i>92.01</i>
Plugging and Abandonment of Boreholes							12-9-9	<u></u> 1	3-21000-0	72.01
Expires _	12/9/9.	3 mcB		Pr	ocedure Rev	ision Required	X	Yes No		
Scope Lin	nitation	none								·
										<u></u>
ltem Number	Page	Step or Paragraph			/Llee D/	ON CONTINUA	Chang		tional Con-	1
MUITIDE	rage	raiayiapii			(USE DI	JN CONTINUA	TION SI	TEET IOF AGGI	tional Spac	ce)
1	6 of 8	paragraph 1 line 7	borings consist	less t of mix	han 10 feet d ing grout acc	ne tremie pipe v leep, where gro cording to the n anical mixer. T	oundwate nanufact	er was not end urer's recomm	ountered, pendations	plugging will either
	-									
	,	,				•		•		
									*	
						•				•
									•	
For shallor quantities	w holes, of grout	_	is not ne	cessa	rvito ensure	DOC PER	ument (ŕ	n addition, on REVIEW SIFICATION	WAIVER OFFICE
Cohcurre	ence	Organizatio	on F	Req	Date	Concurrenc	е	Organization	Req	Date.
ADV.	mit	QAPM		Х	12/9/92	Mar	<u>2</u> ,	User	Х	12/9/92
M.C.B.	oussa	EOM		×	12/8/92	& Guard	-	User	X	12/9/92
						a from		YSER	X	12/9/92
3							~ =			
pproval o	f Bespor	nsible Manage	er D	ate		Is Posting Red	-	es, By What	Date?	Date Posted
				12-8-	122	X Yes	a i i			i

CONTROLLED DOCUMENT EG&G - ROCKY FLATS PLANT

ENVIRONMENTAL MANAGEMENT DOCUMENT CHANGE NOTICE (DCN)

ENVIRONMENTAL MANAGEMENT
This is a RED Stamp 2/000 EAB
Procedure Number 5-51000-OPS-GT.6,Rev2

Page 1 of 1

Title M	ONITORII	NG WELLS AN	D PIEZOMETI	ER INSTALLA	TTION D	ate 11/12/92	DCN Numb 5-21000-0	oer <i>92.06</i> PS-GT.6,Rev
Expires _ Scope Lin	11/12/9	2 /1//2/93*** Operable		Procedure Re	vision Required	☑ Yes ☐ No		
tem Number	Page	Step or Paragraph		(Use I	OCN CONTINUATI	Changes ON SHEET for Addit	ional Space)	
1	6	1	Change the	second senter				
2	- 11	2	sized drive so hole, no more 2-foot deep s Add the follow Before placin the borehole	ampler will be a than 1 inch gediment sump wing to the en	driven 2 to 5 feet in greater than the out of and to classify the driven of the second parameters.	ced to the bedrock c nto the claystone bed tside diameter (O.D.) e bedrock lithology b ragraph: ehole, any void spac sump will be backfille	drock to provi of the casing elow the cont e between the	de a pilot g, for a act. e bottom of
The bor	reholes in	· -{			DOCUMENT	ng items Above) Ine Hial Union is no se CLASSIFICATION F DFFMAN, CLASSIFI ITINF 11 1991	REVIEW WAI'	VER
Concurr	rence	Organization	Req	Date	Concurrence	Organization	Req	Date
	Mount	QAPM	Х	12/10/92	5 Cmark	User	X	11/13/92
11/	Bronne	DEOM	X	12/8/92	Mari	user:	×	12/8/92
/ }{				11	& Rum	User	×	12/9/92
pprovat	of Respo	nsible Manger	Date	192	Is Posting Requ		Date?	Date Posted